

CASE STUDY

A North West Housing Association

Project Management and Contract Administration



Challenge

A housing association in the north west, appointed Sircle to provide project management and contract administration services for the fire precaution investment works that were due to be carried out on a number of their sites across the north west of England. These sites varied in occupancy types, including sheltered, supported, and general needs. The client also required post-inspection/validation work undertaken on previously completed fire-related upgrades and renewals to further sites across the region, following a programme of Fire Risk Assessment (FRAs) works.

Solution

We met with the client to fully understand the scope of service requirements and the brief, which included management of the contractors, providing project monitoring, quality control management, providing regular client updates, programme management and holding performance/progress meetings.

Our experienced Project Management team assisted the client in fulfilling their Construction Design and Management (CDM) duties, as required under the CDM Regulations 2015. This ensured all project work was undertaken safely and in line with all health and safety requirements.

The validation works undertaken included a compliance inspection of various completed fire safety works, as per the agreed scope. The data from the post-inspection survey was captured electronically on-site through bespoke fire safety software on a handheld device.

This survey also assessed the quality, measured in line with the manufacturer's specifications we were provided with. The results of these surveys, which included our findings and recommendations, were submitted electronically to the client in a report format.

Outcome

The fire safety improvement programme we carried out successfully met the project requirements to the agreed

programme and budget, ensuring the housing association maximised its investment within its portfolio.

The work, which included advanced technology smart lighting systems, enhanced upgrades to existing fire alarm systems, and fire compartmentation works, has also allowed the client to achieve the standards required of the British Standard BS5839 parts 1 and 6.

The support Sircle provided contributed to the client successfully closing out their 2021/22 programme.



Insight for the built environment

0333 999 3747

info@sircleuk.com | sircleuk.com



sircle

Our services



Survey Services

Measured Building

Drawing Verification

M&E Asset

M&E Services

Medical Gases

Occupancy

3D Laser Scanning / Point Cloud

Topographical

Building Elevations

Space & Asset Tagging

(GS1)

Drainage / CCTV

GPR / Utilities

Drone

Planned Preventative Maintenance (PPM)

Schedule of Condition

Latent Defect



CAD & BIM

CAD Bureau

Drawings Review, Maintenance & Management

BIM Model Hosting

BIM / Revit Modelling

Drawing Gap Analysis

Drawing Register Creation

Schematic / Isometric Creation

Land Registry Compliant Plans



Scanning

Document Scanning

Document Management System Population

Drawing Scanning (incl. Large Format

Invoice Scanning

Indexing & Bookmarking

OCR

Document Hosting

Legacy Scanning

Compliance Document Scanning

Estates, Facilities & Capital Manual Scanning



Compliance

Fire Fighting Equipment and Asset Surveys

Fire Compartmentation Surveys

Fire Door Surveys

Fire Risk Assessments

Glazing Audits

Window Restrictor Audits

Asbestos Re-

Inspections

Clinical Waste Audits



Project Management

Project Management

Contract Administration



Head Office: Churchill Court, Palmerston Road Bournemouth, Dorset BH1 4HN

Insight for the built environment

0333 999 3747

info@sircleuk.com | sircleuk.com

