

CASE STUDY

Southport Learning Trust



Challenge

Southport Learning Trust is a family of five schools located in and around Southport on Merseyside. The trust appointed Sircle to carry out a series of fire safety surveys, including fire strategy drawings, fire risk assessments (FRAs) and compartmentation surveys at their Maghull High School. The surveys were expedited and required quickly to enable the trust to meet their Condition Improvement Funding (CIF) deadlines and submit costs for the required works.

Solution

The success of this project hinged on lots of data being collected and brought together quickly to allow for rapid survey mobilisation. To achieve this, we swiftly organised a building surveyor to attend and validate the school building plans and confirm any changes to layout and room/space functions. This enabled us to update the drawings and create accurate plans.

Once the plans were accurate, we undertook the compartmentation/fire strategy drawings to understand where the fire doors and fire-rated construction needed to be to ensure life safety and property protection.

These plans assisted our passive fire surveyors, who utilised handheld tablets to collect data against the new plans.

We also coordinated and delivered individual fire risk assessments for the building on site in scope. The identified capital investment works required could then be fed into the school's bid for funding.

These surveys provided both costs and priority risk ratings that helped the trust decide on the urgency of the work required. It also gave them valuable insight into potential costs to achieve fire safety and compliance with the fire safety order.

Outcome

Much of the work was undertaken during term time, meaning there were certain access restrictions. Despite this, we managed to turn the whole survey programme for the trust around within the required deadline for funding applications. We provided the trust with a clear prioritisation of fire safety works required for capital investment, management and

training etc., to assist them with planning and delivering the recommended actions.

We also gave the trust the up-to-date building plans, space utilisation information and Fire Risk Assessments (undertaken by a FRACS accredited Tier 3 IFSM Fire Risk Assessor) they needed.

At the end of the project, we presented the trust with a comprehensive fire door survey and compartmentation information in a professional PDF report. The detailed survey findings were also collated into clear excel spreadsheets with data analysis tabs to assist the client in understanding the high-level issues and trends found, allowing 'at a glance' understanding of large quantities of survey data.

The trust later feedback to us that they were successful in securing the CIF funding they wanted due to the work we did.

Services Provided:

- Fire Risk Assessments (FRAs)
- · Fire Compartmentation Surveys
- Fire Door Surveys
- · Fire Strategy Drawings



Insight for the built environment

0333 999 3747

info@sircleuk.com | sircleuk.com

sircle

sırcle

Our services



Survey Services

Measured Building

Drawing Verification

M&E Asset

M&E Services

Medical Gases

Occupancy

3D Laser Scanning / Point Cloud

Topographical

Building Elevations

Space & Asset Tagging

(GS1)

Drainage / CCTV

GPR / Utilities

Drone

Fabric

Planned Preventative Maintenance (PPM)

Schedule of Condition

Latent Defect



CAD & BIM

CAD Bureau

Drawings Review, Maintenance & Management

BIM Model Hosting

BIM / Revit Modelling

Drawing Gap Analysis

Drawing Register Creation

Schematic / Isometric Creation

Land Registry Compliant Plans



Scanning

Document Scanning

Document Management System Population

Drawing Scanning (incl. Large Format

Invoice Scanning

Indexing & Bookmarking

OCR

Document Hosting

Legacy Scanning

Compliance Document Scanning

Estates, Facilities & Capital Manual Scanning



Compliance

Fire Fighting Equipment and Asset Surveys

Fire Compartmentation Surveys

Fire Door Surveys

Fire Risk Assessments

Glazing Audits

Window Restrictor Audits

Asbestos Re-Inspections

Clinical Waste Audits



Project Management

Project Management

Contract Administration



Head Office: Churchill Court, Palmerston Road Bournemouth, Dorset BH1 4HN

Insight for the built environment

0333 999 3747

info@sircleuk.com | sircleuk.com

